

Pit Status Evaluation Form

Pit Overview:

Pit Name: WOLFE	Facility ID: 113848
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: NONE LISTED	
Updated Operator: BERRY* WALTER V DBA BERRY ENERGY INC - 8005	
Form 15 Pit Permit Doc #: 664506	Permit Date: 12/6/1976
Related Facilities: API # 05-001-07107 (Facility ID 201703), Location 375977	

County: Adams			
Township: 1S	Range: 67W	Section: 22	QQ: NWSE
Original Latitude/ Longitude: NA / NA			
Updated Latitude/ Longitude: 39.955595 / -104.878719			
Basis for Location Change:			
Lat/Long created based on historic aerial imagery (circa 6/1993)			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|--|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 664506 | Date: 12/6/1976 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 200079180 | Date: 4/4/1985 |
| | Doc #: 327751 | Date: 5/28/1998 |
| | Doc #: 1084272 | Date: 9/1/2001 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2229120 | Date: 2/18/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 102336 (CL 8/22/2001) | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/1/2001

Timing of Pit Closure:

Pit was replaced by a fiberglass produced water tank prior to 1998 pit inventory report. Location passed final reclamation inspection 9/1/2001.

Pit Status Review Summary:

Duplicate of pit 102336. Inspections document a 30x30x6 unlined pit on location, which was replaced by a fiberglass water tank prior the 1998 pit inventory report. Wells were plugged and passed final reclamation inspection 9/1/2001. Pit status has been changed to Closed.

