

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2019

Submitted Date:

05/30/2019

Document Number:

687904846

FIELD INSPECTION FORM

Loc ID 311887 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Inspections, All		inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216304	WELL	PR	07/01/2011	GW	067-07910	F W TERRELL GAS UNIT 2	PR
296161	WELL	PR	06/19/2018	GW	067-09559	IGW 122	PR

General Comment:

This is a follow-up inspection in regards to the inspection document# 687903677 and the re-inspection document# 987903773. The following corrective actions not completed as of 5.30.19. Please see attached photos at the end of this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Unused equipment pumping station for produced water tanks. Equipment is not connected and not in service.

Corrective Action: Remove unused equipment or return to operating status per Rule 603.f.

Date: 05/30/2019

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition:

Other (Content):

Other (Capacity):

Other (Type):

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Liner in interior of IGW 122 is inadequate with tearing and holes along north side from east to west and south side from east to west..				
Corrective Action: Repair or install secondary containment devices per Rule 906.d.(1)				
Date: 06/30/2019				

Venting:

Yes/No:

Comment:

Corrective Action:

Date:

Flaring:

Type:

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 216304 Type: WELL API Number: 067-07910 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 296161 Type: WELL API Number: 067-09559 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>This is a follow up inspection to a previous inspection. Follow-up inspection required.</u>	stewartj	05/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402059998	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835967
687904847	Unused equipment in shed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835945
687904848	Unused shed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835946
687904849	Liner holes.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835947
687904850	Liner tears.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835948
687904851	Liner tears.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835949
687904852	Liner holes.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835950