

Maralex Resources Inc.
API # 05-077-08601
Inspection # 696600068



Photo #1 Photo of location at entrance of location

Maralex Resources Inc.
API # 05-077-08601
Inspection # 696600068



Photo # 2 Tank with new tank label



Photo #3 Vegetation growing inside of tank berm

Maralex Resources Inc.
API # 05-077-08601
Inspection # 696600068



Photo #4 Pump Jack with Wellhead sign in place. More rubbish seen on location.

Photo #5 Photo of location used as a storage facility.

Maralex Resources Inc.
API # 05-077-08601
Inspection # 696600068



Photo #6 Wattle in need of maintenance



Photo #7 Photo of erosion channel moving sediment off location at entrance.

Maralex Resources Inc.
API # 05-077-08601
Inspection # 696600068



Photo #8 Photo of culvert covered with vegetation growth on uphill side.



Photo #9 Photo of exit side or downhill side of culvert.