

Maralex Resources Inc.
API # 05-077-08610
Inspection # 696600076



Photo #1 Photo of location from NE entrance of location

Maralex Resources Inc.
API # 05-077-08610
Inspection # 696600076



Photo #2 Photo of location from West side of location

Maralex Resources Inc.
API # 05-077-08610
Inspection # 696600076



Photo #3 of location from West side of location of remaining riser

Photo #4 of location from West side of location, close up of riser and hole left on location

Maralex Resources Inc.
API # 05-077-08610
Inspection # 696600076



Photo #5 of hole marked by 2 t-post on north side of location.



Photo #6 of hole marked by 2 t-post on north side of location.