

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2019

Submitted Date:

06/05/2019

Document Number:

696600064

**FIELD INSPECTION FORM**
 Loc ID 312609 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Enginnering
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

**General Comment:**

This is a follow up inspection from Doc#689401339 dated 6/7/18 and 675001726 dated 1/9/19, and 675002096 dated 3/29/19 . Required Corrective Action (s) items noted in previous inspections have not all been satisfied.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road is being maintained. Blade on access road during inspection.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead sign has been placed at wellhead Corrective action has been made		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label has been updated. Corrective action has been made		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery sign on location		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 07/05/2019
Emergency Contact Number:			
Comment:	970-858-8550 / 911 Lettering fading on wellhead sign		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment or trash stored on location		
Corrective Action:	Comply with Rule 603.f .		Date: 07/05/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	Open Top		,	
Comment:	Fiberglass open top					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 222011 Type: WELL API Number: 077-08613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in, Well last produced April 2010. MIT on 2/19/2015 Doc#400797603.  
No current MIT on file

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 06/17/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion not being controlled on the location at this time. BMP's not in place or maintained. Sediment running onto and off location causing erosion see inspection 675002096 dated 3/29/19</p>						Date: 04/29/2019
<p>Corrective Action: Install or repair required BMPs per Rule 1002.f.</p>						
<p><b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**COGCC Comments**

Comment	User	Date
<p>On Tuesday (Date 06/4/2019) at approximately (1338), I, Inspector Dougo Wentzel, conducted a This is a follow up inspection from doc#675002096 Dated 3/29/19 at (Maralex) (Shale Ridge 7-24), at ( API #077-08613) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed: No Battery sign posted on location Unused equipment or trash stored on location Stormwater BMP's are not in place No current MIT on file., (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/04/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600065	Inspection 696600064 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841945">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841945</a>