

# Inspection Photos

API: 05-061-06363

Operator: ARMOR PETROLEUM INC

Inspection Date: 6/4/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019

## Inspection Photos



**Photo 1.** Dorsett Tank Battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019

## Inspection Photos



**Photo 2.** There are two barrels with no labeling and possible leakage with oil stained soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019



## Inspection Photos



**Photo 3.** There is oil stained soil between the tanks.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019

## Inspection Photos



**Photo 4.** There is oil stain soil at the pipe valve.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019



## Inspection Photos



**Photo 5.** There is oil stained soil around the tank. Tank likely has leak.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019

## Inspection Photos



**Photo 6.** The berm around the north side of the tanks is insufficient for secondary containment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019



## Inspection Photos



**Photo 7.** There is various unused equipment being stored at the south side of tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06363 | Date: 6/4/2019