

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Plunger Lift	# 0			
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Inspected Facilities

Facility ID: 246126 Type: WELL API Number: 014-13923 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
At time of inspection it appears well head has been removed but flow line has not. Forms 42 Doc#401968078 and form 6Doc# 401973160 have been submitted to the COGCC.	silverr	06/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500325	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842675