

Inspection Photos  
Location Name: BEM 32-19  
API#: 05-071-08925  
INSP. #: 695100814



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos  
Location Name: BEM 32-19  
API#: 05-071-08925  
INSP. #: 695100814



**PHOTO 3: AREA OF IMPACTED SOIL APP. 7' BY 3' BETWEEN COMPRESSOR SKID AND PUMPJACK. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



**PHOTO 3: AREA OF IMPACTED SOIL APP. 2' BY 2' ON EAST SIDE OF ENGINE SKID AND PUMPJACK. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**

Inspection Photos  
Location Name: BEM 32-19  
API#: 05-071-08925  
INSP. #: 695100814



**PHOTO 5: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/21/19.**