

Inspection Photos  
Location Name: WOODSTOCK 43-19  
API#: 05-071-08677  
INSP. #: 695100820



**PHOTO 1: WELLHEAD**



**PHOTO 2: WELL SIGN**





Inspection Photos  
Location Name: WOODSTOCK 43-19  
API#: 05-071-08677  
INSP. #: 695100820



**PHOTO 3: AREA OF IMPACTED SOIL APP. 10' BY 5' AROUND COMPRESSOR SKID ON SOUTH SIDE OF COMPRESSOR.**  
**Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



**PHOTO 4: AREA OF IMPACTED SOIL APP. 4' BY 2' ON EAST SIDE OF ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



Inspection Photos  
Location Name: WOODSTOCK 43-19  
API#: 05-071-08677  
INSP. #: 695100820



**PHOTO 5: AREA OF IMPACTED SOIL APP. 6' BY 5' ON NORTH SIDE OF ENGINE SKID EXTENDING UNDER SOUND WALL.**

**Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



**PHOTO 6: AREA OF IMPACTED SOIL APP. 3' BY 2' ON SOUTH SIDE OF PUMPJACK CONCRETE PUMPJACK BASE IS SATURATED WITH WHAT APPEARS TO BE OIL.**

**Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



Inspection Photos  
Location Name: WOODSTOCK 43-19  
API#: 05-071-08677  
INSP. #: 695100820



**PHOTO 7: AREA OF IMPACTED SOIL APP. 3' BY 2' ON EAST SIDE OF PUMPJACK BETWEEN WELL HEAD AND PUMPJACK CONCRETE PUMPJACK BASE IS SATURATED WITH WHAT APPEARS TO BE OIL. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/6/19.**



**PHOTO 8: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/21/19**

Inspection Photos  
Location Name: WOODSTOCK 43-19  
API#: 05-071-08677  
INSP. #: 695100820



**PHOTO 9: SOUND WALLS ARE FALLING DOWN. IT APPEARS THE DOOR IS HOLDING THE SOUND WALLS UP. REMAIR SOUND WALLS IN ACCORANCE WITH 603.f. CA DATE 7/6/19**



**PHOTO 10: IMAGE OF SOUND WALLS ON THE OPPOSITE SIDE FROM PREVIOUS PHOTO. SOUND WALLS ARE CONNECTED ACROSS THE TOP. REMAIR SOUND WALLS IN ACCORANCE WITH 603.f. CA DATE 7/6/19**