

Inspection Photos  
Location Name: LOUIS 41-30  
API#: 05-071-07521  
INSP. #: 695100822



**PHOTO 1: WELLHEAD**

**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: LOUIS 41-30  
API#: 05-071-07521  
INSP. #: 695100822



**PHOTO 3: EROSION THAT APPEARS TO BE CAUSED FROM DRAINING THE SEPARATOR IN THE METER HOUSE AS THE METER HOUSE IS UPGRADE FROM LOCATION AND STORM WATER WOULD TRAVEL AWAY FROM THE METER HOUSE TOWARD THE CENTER OF LOCATION IS UNDERMINING METERHOUSE. REPAIR EROSION AND DISCONTINUE DRAINING SEPARATOR IN LOCATION. CA DATE 7/6/19**

**PHOTO 4: ANOTHER ANGLE OF EROSION NOTED IN PREVIOUS PHOTO.**

Inspection Photos  
Location Name: LOUIS 41-30  
API#: 05-071-07521  
INSP. #: 695100822



**PHOTO 5: EROSION CONTINUEING OF LOCATION. REPAIR  
EROSION AND DISCONTINUE DRAINING SEPARATOR IN  
LOCATION. CA DATE 7/6/19**