

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2019

Submitted Date:

06/06/2019

Document Number:

695100820**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 308815 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282632	WELL	PR	03/20/2006	GW	071-08677	WOODSTOCK 43-19	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: AREA OF IMPACTED SOIL APP. 10' BY 5' AROUND COMPRESSOR SKID ON SOUTH SIDE OF COMPRESSOR. PHOTO 4: AREA OF IMPACTED SOIL APP. 4' BY 2' ON EAST SIDE OF ENGINE SKID. PHOTO 5: AREA OF IMPACTED SOIL APP. 6' BY 5' ON NORTH SIDE OF ENGINE SKID EXTENDING UNDER SOUND WALL. PHOTO 6: AREA OF IMPACTED SOIL APP. 3' BY 2' ON SOUTH SIDE OF PUMPJACK CONCRETE PUMPJACK BASE IS SATURATED WITH WHAT APPEARS TO BE OIL. PHOTO 7: AREA OF IMPACTED SOIL APP. 3' BY 2' ON EAST SIDE OF PUMPJACK BETWEEN WELL HEAD AND PUMPJACK CONCRETE PUMPJACK BASE IS SATURATED WITH WHAT APPEARS TO BE OIL.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907.	Date:	07/06/2019
Type	OTHER		
Comment:	PHOTO 9: SOUND WALLS ARE FALLING DOWN. IT APPEARS THE DOOR IS HOLDING THE SOUND WALLS UP. PHOTO 10: IMAGE OF SOUND WALLS ON THE OPPOSITE SIDE FROM PREVIOUS PHOTO. SOUND WALLS ARE CONNECTED ACROSS THE TOP.		
Corrective Action:	REPAIR SOUND WALLS IN ACCORDANCE WITH 603.f.	Date:	07/06/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	PHOTO 8: Vacuum pump observed on well without COGCC approval.		
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.	Date:	06/21/2019
Type: Bradenhead	# 1		
Comment:	IS NOT PLUMBED TO SURFACE		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 282632 Type: WELL API Number: 071-08677 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100821	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842913