

Inspection Photos

API: 05-017-07774

API: 05-017-07780

Operator: ANADARKO E&P ONSHORE LLC

Inspection Date: 6/5/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 1. Facing north toward the location. There are areas that were recently seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 2. Facing north toward the location. There are areas that were recently seeded and straw mulched.



Inspection Photos



Photo 3. Facing north toward the location. There are areas that were recently seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 4. Facing east toward the location. This area has a dominance of weeds. There are signs the location was interseeded which may help to control the weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 5. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 6. Facing east toward the location. The southern portion has good desirable vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 7. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Date: 6/5/2019

Inspection Photos



Photo 8. View of vegetation establishment containing some weeds and desirable vegetation establishment.

