

Inspection Photos
Location Name: State 16-2
API: 05-081-06194



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Evidence of sediment migration down access road. Photo taken at location perimeter looking away from location.

Inspection Photos
Location Name: State 16-2
API: 05-081-06194



Photo 3. Evidence of sediment migration down access road. Photo taken near location perimeter looking away from location.



Photo 4. Evidence of sediment migration down access road. Photo taken halfway up access road looking away from location.