

Taiga Federal 9-J-21-4S-102W

API: 05-103-08088

Inspection: 679704399



Photo 1. Location.



Taiga Federal 9-J-21-4S-102W

API: 05-103-08088

Inspection: 679704399



Photo 2. Old operator well heads, along with new operator sign.



Photo 3. Tank battery sign with old operator information.

Taiga Federal 9-J-21-4S-102W

API: 05-103-08088

Inspection: 679704399

Tank anchor



Photo 4. Tank.

Photo 5. Bulls located 0.2 mile from well location.

Taiga Federal 9-J-21-4S-102W

API: 05-103-08088

Inspection: 679704399



Photo 6. Fluid in hole created when tank tilted over.



Photo 7. Inside of tank. Top of fluid at spill point of hole.