

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

679600871

FIELD INSPECTION FORM

Loc ID 317495 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238330	WELL	PR	02/01/2019	GW	123-05172	HANKINS 22D	PR
264293	WELL	PR		OW	123-21046	HANKINS 22-42	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Missing BBLS on produced water tank. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 07/03/2019
Type	WELLHEAD		
Comment:	Adequate (x2)		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in fencing of wellhead. See attached photo.		
Corrective Action:	Comply with Rule 603.f.		Date: 07/03/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel (x2)		
Corrective Action:			Date:

Equipment:

Type: Horizontal Heated Separator	# 1			
Comment:	Anchored			
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:

Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.378100,-104.875800
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	238330	Type:	WELL	API Number:	123-05172	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	264293	Type:	WELL	API Number:	123-21046	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday, June 3, 2019 at approximately 9:50, I, Inspector Brittani Santistevan, conducted an on-site inspection at HANKINS 22D, 22-42 (PDC Energy), at location #: 317495 in WELD COUNTY Colorado.</p> <p>While there, I observed producing wellheads.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. No BBLS listed on produced water sign. INSTALL SIGN TO COMPLY WITH RULE 210.D. (Corrective Action Date: July 3, 2019) See attached photo #2 in location photos.</p> <p>2. Unused equipment inside HANKINS 22D fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: July 3, 2019) See attached photo #2 in individual wellhead photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	06/03/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402062862	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838604
679600872	Hankins 22-42	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838596
679600873	Hankins 22D	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838597
679600874	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838598