

Inspection Photos

Location Name: North Platte J-24 Dumpline Release

Facility ID: 429060



Photo 1 – Pipeline has been exposed via hydrovac and is awaiting spill cleanup.



Photo 2 - Salt crust observed on surface soil adjacent to the hydrovac excavation. During site assessment Operator shall characterize impacts to top 0-6" in addition to subsurface impacts.

Inspection Photos

Location Name: North Platte J-24 Dumpline Release

Facility ID: 429060



COGCC Environmental Inspection

Photo 3 – Excavated impacted on plastic liner within berm.



COGCC Environmental Inspection

Photo 4 – Recent rains have caused heavy erosion and sediment migration throughout facility. Spoke with operator and issues were identified prior to COGCC inspection. Repairs pending.

Inspection Photos

Location Name: North Platte J-24 Dumpline Release

Facility ID: 429060



Photo 5 – Stormwater erosion caused by heavy storms have damaged hydromulch and other BMP's throughout facility. Spoke with operator and issues were identified prior to COGCC inspection. Repairs pending.



Photo 6 – Recent storms have also blown a significant amount of weeds on location. Clean up in compliance with Rule 603.f