

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2019

Submitted Date:

06/10/2019

Document Number:

693700189

FIELD INSPECTION FORM

Loc ID 319436 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 88380
Name of Operator: TINDALL OPERATING COMPANY
Address: P.O. BOX 4507
City: ENGLEWOOD State: CO Zip: 80155

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnroilgas@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111628	PIT	AC			-	DOROTHY 1	EI
243480	WELL	PA	04/14/2017	OW	123-11271	DOROTHY 1	EI

General Comment:

[COGCC Environmental Staff inspection of pit closure; Well has been plugged and production equipment remains on location.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Well tubing, ASTs and treater remain on location; well was plugged 4/14/2017		
Corrective Action:	Remove all unused surface equipment and flowline/dumpline risers as required by Rule 1004.	Date:	07/06/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 111628 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 243480 Type: WELL API Number: 123-11271 Status: PA Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	Oily soil has been stockpiled on location, and oily soil remains in pit. Operator has not implemented approved Form 27 for pit closure			
Corrective Action	Handle oily waste from pit and stockpile in accordance with Rule 907.e. and provide disposal documentation on Form 27 Supplemental Report for Remediation #11611			Date: 07/06/2019
Workover	Other	Inadequate		
Comment	Cement from well plugging remains on location			
Corrective Action	Dispose of cement in accordance with Rule 907.f. and provide disposal documentation to COGCC			Date: 07/06/2019

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 111628 Lat: 40.592969 Long: -103.904781

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: 07/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700190	Dorothy 1 Photos 6-6-2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845255