

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2019

Submitted Date:

06/04/2019

Document Number:

696100996

FIELD INSPECTION FORM

Loc ID 306461	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 1001 NOBLE ENERGY WAY City: HOUSTON State: TX Zip: 77070				Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288971	WELL	SI	09/01/2017	OW	123-24709	COCKROFT USX A 11-2	TA

General Comment:

This is a WELL & ABANDONED BATTERY Inspection.
 Well: Temporarily Abandoned (TA).
 Battery: Abandoned & MOST equipment removed except for Gas meter run & riser.
 Abandoned Battery SE corner GPS coordinates: 40.507680,-104.510090
 Reclamation progressing.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds emerging at wellsite. Consider mitigation. Refer to Rule 603.f See photo #1.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2.		
Corrective Action:	Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f.	Date:	09/03/2019

Overall Good: ☐**Spills:**

Type	Area	Volume			
In Containment: No					
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>					
<input type="checkbox"/> Multiple Spills and Releases?					

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	288971	Type:	WELL	API Number:	123-24709	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned (TA). Battery Abandoned. COGCC records indicate last prod: 09/2015. SI/TA well per variance Doc #401474555. (NOBLE). Decommission / LTSI tags for SI/TA status present at wellsite. Locked-Out, Tagged Out. (LOTO).</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On TUE JUN 04, 2019 at approximately 14:05 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: COCKROFT USX A-66N64W /11NWNE Location ID: 306461 Location County: Weld County, Colorado Weather: Cloudy / Damp from prior rain.</p> <p>While there, I observed: 1-Well(s) Temporarily Abandoned (TA). Battery: Abandoned & MOST equipment removed except for Gas meter run & riser. Abandoned Battery SE corner GPS coordinates: 40.507680,-104.510090 Reclamation progressing.</p> <p>Routine Inspection. 1: Corrective Actions observed. 1.) Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2. Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f. Corrective Action Date: 09/03/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Good Housekeeping COMMENT: Weeds emerging at wellsite. Consider mitigation. Refer to Rule 603.f. See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/04/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402064818	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4840309
696100997	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4840299