

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Pipe		
Corrective Action:			Date:

Equipment:

					corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.204450,-104.814500
Comment:					
Corrective Action:				Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 249729 Type: WELL API Number: 123-17532 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>On Tuesday, June 11, 2019 at 10:23, I, Craig Carlile conducted an on-site inspection at: 329566 Operated by: Anadarko While there I observed: Well shut in. Form 6(N), document number: 401886187 has been submitting for plugging. Battery location shared with many other wells and will remain after plugging of this well. Weather: Skies clear, winds calm, temp 71 F Possible compliance issues observed: None This is a summary of the inspection report.</p>	carlilec	06/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003632	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4846298