

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Pit Facility ID #119826 with stained soil and puddle of oil.



Impacted material below the surface of dry portion of pit.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Proximity of stand pipe in relation to pit area.



Ester #1 wellhead with Pit Facility ID #119826 in the background.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



First test trench was dug on northeast side of pit area.



Trench along southeast side of pit contained stained soil.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Moving poly pipe from wellhead connected to stand pipe.



Trench along northwest side with no visual impacts.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Excavating test trench along southwest side of pit.



Impacted material in trench #4, down gradient of pit.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Visual impacts in trench #5 approximately 15' southwest of trench #4.



Beginning seventh test trench approximately 10' southeast of wellhead.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Wire rope and other debris found buried in trench #7.



Grayish blue material with strong hydrocarbon odor discovered at depth.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Stock pile of material removed from trench #7.



Additional test trenches dug to the west and southwest of the wellhead did not have visual impacts.