

Inspection Photos
Location Name: BAA BAA 34-1 & TR
API#: 05-071-08502 & 08710
INSP. #: 695100841



PHOTO 1: ORIGINAL WELLHEAD

PHOTO 2: TR WELLHEAD

Inspection Photos
Location Name: BAA BAA 34-1 & TR
API#: 05-071-08502 & 08710
INSP. #: 695100841



PHOTO 3: WELL SIGNS

PHOTO 4: HYDRAULIC FITTING ON WELLHEAD IS DRIPPING FLUID. SHADOWS ARE MAKING DRIP HARD TO SEE. ARROW IS POINTING OUT A DRIP THAT IS FORMING ON FITTING. Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation" CA DATE 7/11/19.

Inspection Photos

Location Name: BAA BAA 34-1 & TR

API#: 05-071-08502 & 08710

INSP. #: 695100841



PHOTO 5: 3 AREAS OF IMPACTED SOIL NEAR TR ENGINE SKID. ENGINE SKED ON THE NORTH SIDE OF LOCATION AS THE WELLHEADS ARE NOT MARKED. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/11/19.

PHOTO 6: 2' AREA OF IMPACTED SOIL NEAR TR WELLHEAD. WELLHEAD ON THE NORTH SIDE OF LOCATION AS THE WELLHEADS ARE NOT MARKED. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/11/19.