

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2019

Submitted Date:

06/05/2019

Document Number:

696200161**FIELD INSPECTION FORM**Loc ID 327361 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246765	WELL	SI	01/01/2019	OW	123-14562	SOONER UNIT 6-21	RI
327361	LOCATION	AC			-	SOONER UNIT-68N58W 21SENW	RI

**General Comment:**[This is a follow-up good housekeeping inspection.](#)[This inspection is to document compliance for the following corrective actions:](#)[603.f: Noxious weed management](#)[Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Erosion degradation and sediment transport from the main east/west access road. See photos 4-5 in the attached photo document.		
Corrective Action	Install or repair required BMPs per Rule 1002.f.	Date:	07/05/2019

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	WEEDS		
Comment:	Previous inspections documented Noxious weeds (Diffuse Knapweed, Centaurea diffuse, and Scotch Thistle, Onopordum acanthium) along access roads and location, and required operator to manage and remove.  Operator has failed to conduct sufficient ongoing weed management. Diffuse Knapweed remains evident on location and access roads (including main access road).  Original corrective action and date remains applicable.		
Corrective Action:	Properly remove and control noxious weeds. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.	Date:	06/22/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: <u>246765</u>	Type: <u>WELL</u>	API Number: <u>123-14562</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>327361</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402065807	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841360</a>
696200162	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841332">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841332</a>