

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2019

Submitted Date:

06/11/2019

Document Number:

688304828**FIELD INSPECTION FORM**
 Loc ID 317039 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5659	tcrumley@comcast.net	
Reid, Marta	(303) 893-2438	marta@westernoperating.com	Designated Agent
James, Steve	(303) 893-2438	steve@westernoperating.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234842	WELL	PR	09/01/1957	OW	121-06982	J KENNEDY 1	PR

General Comment:

Routine Inspection

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at gate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Fiberglass produced water tank labels need maintenance (see attached photo).		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-893-2438

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Engine leak in well shed and stained soil at muffler (see attached photos).		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	06/17/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	wire mesh panels		
Corrective Action:		Date:	
Type	PIT		

Comment:			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	shed, bermed (tin pieces are blowing off shed)		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	30 psi		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	gas scrubber, 2 chemical containers		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine, shed (door blown down)		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	See pit section for tank berm maintenance.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLS	STEEL AST		40.136330,-103.184230
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities									
Facility ID:	234842	Type:	WELL	API Number:	121-06982	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Feb 2019 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: 40.136360Long: -103.182930Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Pit berms on east side are going into field under fence and animal holes in fiberglass tank berms (see attached photos).Corrective Action: Install or repair required BMPs per Rule 1002.f.Date: 07/10/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304853	Western Operating J Kennedy 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4847221