

Inspection Photos

API: 05-055-06035

Operator: OXY USA INC

Inspection Date: 6/11/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 6/11/2019

Inspection Photos



Photo 1. The operator name on well sign is not legible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 2. Facing west along the access road toward the wellsite. There are numerous noxious weeds (Canada thistle) in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 3. Facing southwest near the well site. There is a area of noxious weeds (Hoary crest) in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 4. Facing southeast between the two well sites. There are numerous noxious weeds (Canada thistle) in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 5. Facing down the access road. There is an erosion channel that has developed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019