

# Inspection Photos

API: 05-055-06037

Operator: OXY USA INC

Inspection Date: 6/11/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019

## Inspection Photos



**Photo 1.** Facing northeast along the main access road. There are numerous noxious weeds (Canada thistle) along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019

## Inspection Photos



**Photo 2.** Facing southeast along the main access road. There are numerous noxious weeds (Canada thistle) along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019

## Inspection Photos



**Photo 3.** Facing east toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019

## Inspection Photos



**Photo 4.** Facing south toward the interim reclamation area. Vegetation is well established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019

## Inspection Photos



**Photo 5.** Facing north along the hill side at the location. There are numerous noxious weeds (Canada thistle) in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/11/2019