

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/06/2019

Document Number:

696600070

FIELD INSPECTION FORM
 Loc ID 312610 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Colby, Lou		lou.colby@state.co.us	All Reclamation
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222012	WELL	SI	05/01/2010	GW	077-08614	SOUTH SHALE RIDGE 5-23	TA

General Comment:

This is a follow up inspection from Doc#675002140 dated 4/8/19 . Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	No sign at well head at this time.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/10/2019

Emergency Contact Number:

Comment:	911 / 970-858-8550		
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	All Production, Pump Jack, Gas Meter Run, tank and separator equipment stored on location		
Corrective Action:	Comply with Rule 603.f .	Date:	07/10/2019
Type	DEBRIS		
Comment:	Weeds and debris on location		
Corrective Action:	Comply with Rule 603.f .	Date:	10/08/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	#		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	#		
Comment:	All equipment is disconnected and set aside on location		
Corrective Action:		Date:	
Type: Vertical Separator	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	200 BBLs	Open Top		
Comment: fiberglass open top tank is disconnected and set to side of location.					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 222012 Type: WELL API Number: 077-08614 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: All production equipment has been diconenected and removed from wellhead, noted on previous inspection Doc#689400348 from 9/26/17.

No current MIT on record or delinquent as required by Rule 326c

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 10/08/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Seeding	Pass					
		Gravel				

Comment: Stormwater erosion being controlled on the location at this time.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Wednesday) (Date 06/05/2019) at approximately (1115), I, Inspector Dougo Wentzel, conducted a (A Follow up Inspection) at (Maralex) (South Shale Ridge 5-23), at (API #077-08614) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed: Vegetation growth around wellhead and Debris (weeds) on location. Stored and unused equipment on location No current MIT on file., (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402066458	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841956
696600071	Inspection 696600070 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841947