

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2019

Submitted Date:

06/13/2019

Document Number:

696101025

**FIELD INSPECTION FORM**

Loc ID 330667 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10112  
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
 Address: 5057 KELLER SPRINGS RD STE 650  
 City: ADDISON State: TX Zip: 75001

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Beard, Alyssa		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251634	WELL	SI	08/01/2017	GW	123-19437	D.O.C. SHOWERS 32-12-10	PA
274748	PIT	AC	11/19/2004		-	DOC SHOWERS	AC

**General Comment:**  
 This is a **PLUGGED & ABANDONED WELL & INACTIVE BATTERY** Inspection.  
 No equipment at wellsite. Reclamation progressing.  
 Battery is Inactive & ALL equipment shut-down.  
 Pit has been abandoned & removed.  
 Centralized Battery formerly served 2 Location IDs (330667, 330670).  
 (2 - wells ; Plugged & Abandoned - PA).  
 Follow-up to Field Inspection Report Doc. #691200362 dated 08/23/2018.  
 Inactive Battery SE Corner GPS coordinates: 40.611643, -104.123409

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	PBV-Plastic 55-gal. drum appears to be used as a scrubber drip for wet gas residue at treater-separator house.		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		

Comment:	Disconnected, unpainted, unmarked, untagged, unlocked, Bull-plugged: 2 risers at crude oil tanks, (Behind West crude oil tank).		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery formerly served 2 Location IDs (330667, 330670).				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		40.611681,-104.123865
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Prior Insp: Inadequate berms around H2O tank. Refer to Rule 605.a.(4). Repair or install berms or other secondary containment devices. Comply w/ Rule 605.a.(4). Original Corrective Action date: 08/22/2016.  This insp: * H2O tank NOW has adequate berms installed. See photos #3, 4.			
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.611643,-104.123409
Comment:	Equalizer line connects the 2 crude oil tanks.				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 251634 Type: WELL API Number: 123-19437 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Appears Plugged & Abandoned (PA). No equipment at wellsite.  
Pit has been abandoned & removed.  
Reclamation appears progressing.  
Form 6 Doc. #401782440 indicates plugging date: 09/07/2018. Approval Pending.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 274748 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: \_\_\_\_\_      Pit ID: 274748      Lat: 40.611664      Long: -104.124194

Reference Point: SE      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: This pit appears to have been abandoned & closed. Former pit area is entirely flat and filled in.

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 06/12/2019 at approximately 14:53 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: FOUNDATION ENERGY MANAGEMENT LLC                      Location Name: D.O.C. SHOWERS-68N60W /32NWSW                      Location ID: 330667                      Location County: Weld County, Colorado                      Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Plugged &amp; Abandoned (PA).                      No equipment at wellsite.                      Reclamation progressing.                      Battery is Inactive &amp; ALL equipment shut-down.                      Pit has been abandoned &amp; removed.                      Inactive Battery SE Corner GPS coordinates: 40.611643, -104.123409                      Centralized Battery formerly served 2 Location IDs (330667, 330670).                      (2 - wells ; Plugged &amp; Abandoned - PA).                      Follow-up to Field Inspection Report Doc. #691200362 dated 08/23/2018.</p> <p>1 of 1 Corrective Actions appears addressed.                      1.) Inadequate berms around H2O tank. Refer to Rule 605.a.(4).                      Repair or install berms or other secondary containment devices.                      Comply w/ Rule 605.a.(4).                      Original Corrective Action date: 08/22/2016.                      * H2O tank NOW has adequate berms installed.                      See photos #3, 4.</p> <p>NO - NEW Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>06/13/2019</p>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101026	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849114</a>