

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2019

Submitted Date:

06/07/2019

Document Number:

688304778

**FIELD INSPECTION FORM**

Loc ID 317094 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 31257  
Name of Operator: FRITZLER RESOURCES INC  
Address: P O BOX 114  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236155	WELL	PR	02/01/2017	OW	121-08645	CHAS JOLLY 1	SI

**General Comment:**

[Routine Inspection](#)

[See also inspection #688000221 for corrective action. Form 27S was submitted to COGCC database.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	maintain contents label on black, produced water, fiberglass tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-867-1268	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	middle tank valve leaking on west side (see attached photo)		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 07/08/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	steel panels		
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device		# 1		
Comment:	Submit Form 4 VENT_FLARE to COGCC Engineering.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator		# 1		
Comment:	bermed			

Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	bermed shed, propane		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient				
Comment: cows were in berms							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	200 BBLs	STEEL AST		,		
Comment: two enardo valves							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment: same berms as 300 bbl crude oil tank							
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No							
Comment:							
Corrective Action:							
						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:							
						Date:	

**Location Construction**

Location ID: 236155 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 236155 Type: WELL API Number: 121-08645 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Skimming/Settling      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation:      2+ feet Freeboard:

Comment: excavated pit (see attached photos)

Corrective Action

Date:

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition: \_\_\_\_\_

<b>Comment:</b>		<b>Date:</b>
<b>Corrective Action</b>		
<b>Anchor Trench Present:</b>	<b>Oil Accumulation:</b> <u>NO</u>	<b>2+ feet Freeboard:</b> <u>YES</u>
<b>Comment:</b>	<u>dry, south pit</u>	
<b>Corrective Action</b>		<b>Date:</b>
<b>Type:</b> <u>Produced Water</u>	<b>Lined:</b> <u>NO</u>	<b>Pit ID:</b>
	<b>Lat:</b>	<b>Long:</b>
<b>Reference Point:</b> _____	<b>Other:</b> _____	<b>Length:</b> _____
		<b>Width:</b> _____
<b><u>Lining:</u></b>		
<b>Liner Type:</b>	<b>Liner Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b><u>Fencing:</u></b>		
<b>Fencing Type:</b>	<b>Fencing Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b><u>Netting:</u></b>		
<b>Netting Type:</b>	<b>Netting Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b>Anchor Trench Present:</b>	<b>Oil Accumulation:</b> <u>NO</u>	<b>2+ feet Freeboard:</b> <u>YES</u>
<b>Comment:</b>	<u>north pit after tanks</u>	
<b>Corrective Action</b>		<b>Date:</b>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402067803	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843238</a>
688304824	Fritzler Chas Jolly 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843215</a>