

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2019

Submitted Date:

06/07/2019

Document Number:

688304825**FIELD INSPECTION FORM**Loc ID 432065 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 202 TRAVIS STREET #402City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432058	WELL	PR	01/01/2019	OW	073-06520	TAOS 1-10	SI

General Comment:Spill Inspection

Approximately 20 bbls of oil spilled at wellhead from a stuffing box leak overnight. Notifications, cleanup and Form 19I were in process. Operator shall provide root cause of spill and prevention procedures (lessons learned) on Form 19 Subsequent to COGCC EPS within 10 days of spill as required per Rule 906.b

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at CR		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	>= 5 bbls	
Comment:	Stuffing box leak of ~20 BBLs on location was reported to inspector at ~8 am on 6/7/2019. COGCC EPS, landowner and Lincoln County LGD were being contacted by D90's main office. Free fluids were removed from location by D&D; earth berms were put around stained soils at wellhead; and backhoe, loader and roustabouts were working to remove stained soil that will be put in rolloff containers and properly disposed of. Stained soil area between deadmen was ~100'x130'. Workover rig was still set up at wellhead and was being cleaned of oil. South wind blew oil mist onto winter wheat off location to the north side. See attached photos.		
Corrective Action:	Per Rule 906.b. 24 hours to remove free fluids. Twenty-four hours for notification and 72 hours for Initial Form 19 Report. Contact COGCC EPS about requirements of confirmation soil sampling to be submitted.		Date: 06/10/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 432058 Type: WELL API Number: 073-06520 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI for spill. Mar 2019 production last reported to COGCC database.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402068662	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844184
688304831	D90 Energy LLC, Taos 1-10	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844183