

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2019

Submitted Date:

06/14/2019

Document Number:

685101137**FIELD INSPECTION FORM**

Loc ID 434990 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434989	WELL	PR	06/22/2014	OW	123-38406	BADDING 27N-26HZ	PR
434991	WELL	SI	07/01/2018	OW	123-38407	BADDING 2N-26HZ	SI
434992	WELL	PR	06/11/2014	OW	123-38408	BADDING 28C-26HZ	PR
434993	WELL	PR	06/23/2014	OW	123-38409	BADDING 36C-35HZ	PR
434994	WELL	PR	06/22/2014	OW	123-38410	BADDING 15N-35HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Type LOCATION

Comment: 4' Barb wire/Brown fabricated

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run

4

Comment:

Corrective Action:

Date:

Type: Bradenhead

5

Comment:

Corrective Action:

Date:

Type: Vertical Separator

2

Comment:

Corrective Action:

Date:

Type: Bird Protectors

20

Comment:

Corrective Action:

Date:

Type: Compressor

2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

5

Comment:

Corrective Action:

Date:

Type: VRT

2

Comment:

Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	Electric boxes/Automation		
Corrective Action:		Date:	
Type: VRU	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	200 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with oil tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	300 BBLS	STEEL AST		40.108590,-104.743100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>434989</u>	Type: <u>WELL</u>	API Number: <u>123-38406</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434991</u>	Type: <u>WELL</u>	API Number: <u>123-38407</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>434992</u>	Type: <u>WELL</u>	API Number: <u>123-38408</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434993</u>	Type: <u>WELL</u>	API Number: <u>123-38409</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434994</u>	Type: <u>WELL</u>	API Number: <u>123-38410</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection.	medinaj	06/14/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101138	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850448