

Pit Status Evaluation Form

Pit Overview:

Pit Name: STERKEL 1	Facility ID: 114326
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: J M RESOURCES INC / 44155	
Updated Operator: BAYSWATER EXPLORATION & PRODUCTION LLC	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: API # 05-001-07315 (Facility ID 201911), Location 319926	

County: Adams			
Township: 1S	Range: 68W	Section: 1	QQ: NENW
Original Latitude/ Longitude: 39.998678 / -104.952194			
Updated Latitude/ Longitude: 39.996803 / -104.787522			
Basis for Location Change: Location updated based on historic aerial imagery			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes: 	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|------------------|
| <input type="checkbox"/> Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 664607 | Date: 3/8/1986 |
| Doc #: 664608 | Date: 2/19/1989 |
| Doc #: 313378 | Date: 5/25/1998 |
| <input checked="" type="checkbox"/> Form 27 Remediation Workplan – Project #: 7390 | Date: 10/22/2012 |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2314547 | Date: 2/11/1998 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 7/23/2015

Timing of Pit Closure:

Produced water vault removed under remediation project #7390, closed 7/23/2015

Pit Status Review Summary:

Based on records review and aerial photos, the produced water pit was replaced by a concrete vault in the same location. The vault was removed, and pit/vault impacts were remediated under project #7390, closed 7/23/2015. Pit status has been changed to closed.



