



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Green Fencing around wellhead

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Deadman # & Marked

# 4

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 200712 Type: WELL API Number: 001-06115 Status: IJ Insp. Status: IJ

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>DSND</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>11/20/2013</u>
			AnnMTReq: _____

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: Fail Leak Type: \_\_\_\_\_

Comment: 5 year MIT expired on 11/20/18. No current MIT on record or delinquent as required by Rule 326.

Corrective Action: Contact dnr\_cogcengineering@state.co.us with resolution plan. Date: 06/21/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On 6/10/19 at approximately 1310 I, Inspector Justin Medina conducted an on-site inspection at HRM Resources II- 001-06115 -UPRR linnebur 2-19 in Adams County Colorado.  While there, I observed UIC well  During this inspection the following possible compliance issues were observed:  5 year MIT expired on 11/20/18. No current MIT on record or delinquent as required by Rule 326.  Contact <a href="mailto:dnr_cogccengineering@state.co.us">dnr_cogccengineering@state.co.us</a> with resolution plan.  6/21/19  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.  Continuing Education Inspection</p>	medinaj	06/11/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402070502	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845981">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845981</a>
685101091	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845975</a>