

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/11/2019

Document Number:

687904896

FIELD INSPECTION FORM

Loc ID 432377 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100178

Name of Operator: D J SIMMONS INC

Address: P.O. BOX 1469

City: FARMINGTON State: NM Zip: 87499

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Telecky, Barbara		btelecky@blm.gov	Durango
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Seale, Rod		rseale@djsimmons.com	Pet. Eng./Operations Mgr

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432376	WELL	SI	10/01/2015	OW	033-06174	Pinto 1-7	TA

General Comment:

Site inspection with photos at the end of this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels posted on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Flowlines from production tanks, separator, and production tanks are all unused equipment and must be removed. Location has not produced since October/2015 See Photo # 5,6,8,10		
Corrective Action:	Remove unused equipment per Rule 603.f.	Date:	09/11/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No <input type="text"/>				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,

Comment:	Produced water tank is disconnected from process and not in use. See unused equipment tab above for CA and date.		Date:	
Corrective Action:			Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		
Comment:	Crude oil tanks are disconnected from process and are not in use. See unused equipment tab above for CA and date.				Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 432376 Type: WELL API Number: 033-06174 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Production equipment removed from location. Location has not produced since October/2015Corrective Action: Produce well after performing successful MIT or plug per Rules 326 and 319.b. Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail	Compaction	Pass			
Rip Rap	Fail					

Comment: [Stormwater BMP's along southern edge of location are not adequate. See photo#10](#)Corrective Action: [Install or repair required BMP's per Rule 1002.f.\(2\)](#)

Date: 07/11/2019

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402070304	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845760
687904897	Pinto 1-7 inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845753