

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

687904902

**FIELD INSPECTION FORM**

Loc ID 322092 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments5 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Seale, Rod		rseale@djsimmons.com	Pet. Eng./Operations Mgr
Labowskie, Steve		steve.labowskie@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Telecky, Barbara		btelecky@blm.gov	Durango

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208940	WELL	SI	01/01/2017	GW	033-06045	SQUAW CANYON-FEDERAL 2	SI

**General Comment:**

Site inspection with photos at the end of this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards are deteriorated and not legible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/11/2019
Type	WELLHEAD		
Comment:	Sign posted at meter house building.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on sign.	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Thick weeds around separator equipment.		
Corrective Action:	Remove weeds per Rule 603.f.	Date:	06/21/2019

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 1				
Comment:	Wildlife bird protection on Heated Steel tank is not there and vent stack is covered with a bucket.				
Corrective Action:	Install proper wildlife protection per Rule 324.A.a.				Date: 06/21/2019
Type: Flow Line	# 4				
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator dump valve to Produced water tank. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite gathering system.				
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	STEEL AST		,
Comment:	Gauge hatch left open on southern most tank.				
Corrective Action:	Close gauge hatch per Rule 605.a.(9)				Date: 06/13/2019

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 208940 Type: WELL API Number: 033-06045 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No MIT on file. Last reported production date was October/2016. Warning letter issued 3/22/19 with CA date of 6/20/19.

Corrective Action: Comply with warning letter #401963952. Date: 06/30/2019

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402070305	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845761</a>
687904903	Squaw Canyon Federal 2-18	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845757</a>