

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/11/2019

Document Number:

696600104**FIELD INSPECTION FORM**
 Loc ID 334451 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290617	WELL	PR	05/16/2007	GW	077-09288	NORTH VEGA 27-431	PR
291424	WELL	PR	07/17/2007	GW	077-09334	DELTA 27-321	PR
291428	WELL	PR	07/17/2007	GW	077-09335	DELTA 27-314	PR
291429	WELL	PR	07/17/2007	GW	077-09336	DELTA 27-421	PR
292063	WELL	PR	08/28/2007	GW	077-09383	DELTA 27-334	PR
292064	WELL	PR	08/28/2007	GW	077-09382	DELTA 27-324	PR
292065	WELL	PR	08/28/2007	GW	077-09381	DELTA 27-434	PR
292066	WELL	PR	08/28/2007	GW	077-09380	DELTA 27-424	PR

General Comment:

This is a follow up inspection from doc# 675001982 Dated 2/21/19
Corrective actions from previous inspection have been made.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Corrective action from previous inspection has been made.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / 1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 7	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	holes(s) in secondary tank containment liner			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 07/11/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
Corrective Action:					
Corrective Action:					

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Same as tank containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					
Corrective Action:					

Paint

Condition	
Other (Content)	

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	290617	Type:	WELL	API Number:	077-09288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	291424	Type:	WELL	API Number:	077-09334	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	291428	Type:	WELL	API Number:	077-09335	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	291429	Type:	WELL	API Number:	077-09336	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	292063	Type:	WELL	API Number:	077-09383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	292064	Type:	WELL	API Number:	077-09382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	292065	Type:	WELL	API Number:	077-09381	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	292066	Type:	WELL	API Number:	077-09380	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			

Producing Well			
Comment:	Producing Well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					
		Check Dams	Pass			
		Gravel	Pass			
Berms	Pass					
Ditches	Pass					
Gravel	Pass					
Culverts	Pass					
		Compaction	Pass			
Drains	Pass					

Comment: At time of inspection stormwater Erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Monday, 06/10/2019) at approximately (1155), I, Inspector Dougo Wentzel, conducted a (A Follow up Inspection) at the (Laramie) (North Vega 27-431), at (API #077-09288) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed:</p> <p>Holes in containment liner Corrective actions from previous inspection have been made. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402070387	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845834
696600105	Inspection 696600104 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845829