

Inspection Photos

ID: 441082

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 6/14/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 1. Facing toward location sign which indicates incorrect operator name and emergency contact. Missing information.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 2. Unused GMR shed stored onsite has not been removed per previous inspection #[678300126](#) .



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 3. The fence around the location is in disrepair. There is various jagged scrap metal and pipe laying at the entrance of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 4. Facing northwest at the location. Soil pile is full of weeds. Unused areas are not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 5. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 6. There is numerous abandoned pipe risers at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 7: Southeast side of location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019

Inspection Photos



Photo 8. There is numerous abandoned pipe risers at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 6/14/2019