

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2019

Submitted Date:

06/19/2019

Document Number:

685101184

FIELD INSPECTION FORM

Loc ID 311327 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
9 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
,		dnr_cogccengineering@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccenforcement@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241928	WELL	PR	08/13/1979	GW	123-09719	JOHN A. KUNZMAN 4	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Packing appears to be leaking on tubing see pic2,3,4 delinquent as of 12/16/18		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	12/16/2018
Type	OTHER		
Comment:	Well head appears to be leaking see pic2,3,4 delinquent as of 12/16/18		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	12/16/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric boxes		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	bubbles coming out of wellhead see pic 2,3,4 delinquent as of 12/16/18		
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.	Date:	06/19/2018

Flaring:

Type		
------	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 241928 Type: WELL API Number: 123-09719 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width:90%;" type="text" value="road is in wheat field"/>						Date: _____
Corrective Action: <input style="width:90%;" type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On 6/19/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at KPK- API-123-09719 John A Kunzman #4 in Weld County Colorado. While there, I observed producing well This is a follow up inspection from document # 691401549 , 688401283 , 685100760 , 685101051 Corrective Actions are Delinquent from previous 4 inspections. During this inspection the following possible compliance issues were observed: Well head appears to be leaking see pic2,3,4 delinquent as of 12/16/18 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Packing appears to be leaking on tubing see pic2,3,4 delinquent as of 12/16/18 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. bubbles coming out of wellhead see pic 2,3,4 delinquent as of 12/16/18 Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. Bull plug, and stained soil appears to have been addressed. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	medinaj	06/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101185	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854513