

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

06/18/2019

Document Number:

679601028

FIELD INSPECTION FORMLoc ID 435175 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435172	WELL	PR	05/19/2015	OW	123-38493	Weld 152 41-10CHZ	PR
435173	WELL	PR	04/03/2015	OW	123-38494	Weld 152 41-10NHZ	PR
435174	WELL	PR	10/31/2017	OW	123-38495	Weld 152 31-10CHZ	PR
435189	WELL	PR	04/03/2015	OW	123-38501	Weld 152 C-10CHZ	PR
435190	WELL	PR	04/06/2015	OW	123-38502	Weld 152 C-10NHZ	PR
435191	WELL	PR	04/07/2015	OW	123-38503	Weld 152 31-10NHZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	No sign to identify battery is associated with wellheads on location.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/18/2019
Type	WELLHEAD		
Comment:	Adequate (x6)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	(3) tanks do not contain placards/labeling. See attached photos		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/18/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in each separator house. See attached photos		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	07/18/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 6	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment:	Methanol pumps in self containment	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 3	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 6	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		40.501900,-104.883300
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	435172	Type:	WELL	API Number:	123-38493	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435173	Type:	WELL	API Number:	123-38494	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435174	Type:	WELL	API Number:	123-38495	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435189	Type:	WELL	API Number:	123-38501	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435190	Type:	WELL	API Number:	123-38502	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435191	Type:	WELL	API Number:	123-38503	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday, June 18, 2019 at approximately 13:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at WELD 152 PAD (SRC Energy), at location #: 435175 in WELD COUNTY Colorado.</p> <p>While there, I observed producing wells. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. (3) tanks do not have placarding/labeling. INSTALL SIGN TO COMPLY WITH RULE 210.D. (Corrective Action Date: July 18, 2019) See attached photo #2-4. 2. Tank Battery does not contain sign to identify that wellheads on location are associated with tank battery. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: July 18, 2019) See attached photo #1. 3. Stained soil in each separator house. PROPERLY TREAT OR DISPOSE OF OILY WASTE IN ACCORDANCE WITH 907.E. (Corrective Action Date: July 18, 2019) See attached photos #5-10. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection</p>	santistb	06/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601029	Weld 152 #31-10CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855114
679601030	Weld 152 #31-10NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855115
679601031	Weld 152 #41-10CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855116
679601032	Weld 152 #41-10NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855117
679601033	Weld 152 #C-10CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855118
679601034	Weld 152 #C-10NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855119
679601035	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855120