

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2019

Submitted Date:

06/14/2019

Document Number:

679704488**FIELD INSPECTION FORM**Loc ID 316219 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone        | Email                      | Comment |
|-------------------|--------------|----------------------------|---------|
| Thompson, Philana | 505-324-5300 | pthompson@merrion.bz       |         |
| Kellerby, Shaun   | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 257431      | WELL | SI     | 10/01/2018  | OW         | 103-10025 | PARK MOUNTAIN 4-18 | SI          |

**General Comment:**[COGCC Inspection Report Summary.](#)[On 6-13-2019 at approximately 14:45, inspector Rick Moran, conducted a routine well inspection at Merrion Oil & Gas well Park Mountain 4-18 in Rio Blanco county.](#)[During this inspection the following compliance issues were observed:](#)[1\) Nearest public road & 911 on sign. Photo 2. Complete by 8-12-2019.](#)[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679704488.](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | BATTERY  |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |
| Type               | WELLHEAD   |       |            |
| Comment:           | Sign not posted or information inaccurate at well(s) or battery<br>Missing nearest public road (CR 109) and "911". |       |            |
| Corrective Action: | Install sign to comply with Rule 210.b.  | Date: | 08/12/2019 |
| Type               | TANK LABELS/PLACARDS   |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |

**Emergency Contact Number:**

|                    |              |             |
|--------------------|--------------|-------------|
| Comment:           | 505-324-5300 |             |
| Corrective Action: |              | Date: _____ |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Type               | PUMP JACK |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

**Equipment:**

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
|                          |     |       | corrective date |
| Type: Gas Meter Run      | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Deadman # & Marked | # 4 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Bird Protectors    | # 2 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Pump Jack          | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

|                                   |     |  |       |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |

**Tanks and Berms:**

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | 39.791900,-109.004700 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate |                     |                     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 257431 | Type: | WELL | API Number: | 103-10025 | Status: | SI | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: <div>Last recorded production September 2018.</div>   |        |       |      |             |           |         |    |               |    |
| Corrective Action: <div></div> Date: _____   |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402075950    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850710</a> |
| 679704489    | inspection photo     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850702">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850702</a> |