

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

06/23/2019

Document Number:

688304898**FIELD INSPECTION FORM**
 Loc ID 317146 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pivonka, Todd	(970) 667-9861	timkaresources@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236820	WELL	PR	04/20/2011	OW	121-09314	THEURER-FEDERAL 32-28	PR

General Comment:

Routine Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	the word Federal is faded out on the well sign		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-590-5617

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	steel panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	riser on/near access road		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	electric motor	Date:	
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	shed, berms, chemical container	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	chemical container	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	fiberglass				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same berms as 300 bbl produced water tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.200340,-103.201230
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities			
Facility ID: 236820	Type: WELL	API Number: 121-09314	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	PR. May 2019 production reported to COGCC database.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:Fencing Type: None

Fencing Condition: _____

Comment: CRP

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: NO2+ feet Freeboard: YES

Comment: _____

Corrective Action: _____

Date: _____

Type: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:Fencing Type: None

Fencing Condition: _____

Comment: CRP

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Inspector Name: Sherman, Susan

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304983	Timka Theurer-Federal 32-28	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858514