

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2019

Submitted Date:

06/18/2019

Document Number:

689900891

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
LEVENGOD JOHN		jlevengood07@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412232	PIPELINE	AC	05/04/1998		-	BACA GAS GATHERING SYSTEM 412232	RI

General Comment:

[This is a location inspection.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location sign shows incorrect operator.		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 07/18/2019
Emergency Contact Number:			
Comment:	Emergency contact is missing		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 07/18/2019
Good Housekeeping:			
Type	OTHER		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . Remove pipe risers.		Date: 07/18/2019
Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment on location. 2 GMR sheds, pipe, scrap metal.		
Corrective Action:	Comply with Rule 603.f . Remove unused equipment.		Date: 07/18/2019
Type	WEEDS		
Comment:	There are weeds growing around the equipment and on soil pile.		
Corrective Action:	Comply with Rule 603.f . Control weed growth.		Date: 07/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	The fence around the location is in disrepair.		
Corrective Action:	Comply with 1002.a.3. Repair fence.		Date: 07/18/2019
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402079514	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4853599
689900892	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4853592