

# Inspection Photos

API: 05-061-06076

Operator: CHEMCO INC

Inspection Date: 6/21/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

## Inspection Photos



**Photo 1.** Facing southwest along the former access road. Crop is not establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

## Inspection Photos



**Photo 2.** There is a cement pad and pipe risers and shed that remain just north of the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

Inspection Photos



**Photo 3.** View of the abandoned shed and pipe risers.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

## Inspection Photos



**Photo 4.** Abandoned pipe riser near the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

## Inspection Photos



**Photo 5.** Crop is not establishing near the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019

## Inspection Photos



**Photo 6.** Facing north at the well site. Crop is not growing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 6/21/2019