

Inspection Photos
Location Name: Peppler Fee Com 12-18
API: 05-081-06857



Photo 1. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: Peppler Fee Com 12-18
API: 05-081-06857



Photo 2. Wellhead LOTO.



Photo 3. Unmarked risers.

Inspection Photos
Location Name: Peppler Fee Com 12-18
API: 05-081-06857



Photo 4. Debris in tank battery.



Photo 5. Unmarked riser and stained soil in tank battery.