

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2019

Submitted Date:

06/26/2019

Document Number:

696101053**FIELD INSPECTION FORM**

Loc ID 306382	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1001 NOBLE ENERGY WAY</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77070</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288246	WELL	SI	04/01/2017	OW	123-24562	FOSS - USX AA 5-25	TA

General Comment:

This is a WELL & BATTERY inspection.
 Well is Temporarily Abandoned (TA).
 Battery: Abandoned, ALL equipment removed.
 Reclamation progressing.
 Abandoned Centralized Battery formerly served 2 Location IDs (306382, 310381).
 (2 - wells ; Temporarily Abandoned (TA)).
 Abandoned Battery GPS Coordinates SE Corner: 40.515428, -104.469150
 Follow-up to Field Inspection Report Doc. #684905466 dated 05/24/2018.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Emergency number at wellsite is NOT valid. Refer to Rule 210.b. See photo #2			
Corrective Action:	Post valid emergency number at wellsite. Comply w/ Rule 210.b. See photo #2			Date: 07/26/2019
Good Housekeeping:				
Type	OTHER			
Comment:	<p>Prior insp: Stained soil at crude oil tank loadout. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at crude oil tank loadout. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018.</p> <p>This insp: * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.</p>			
Corrective Action:			Date:	
Type	WEEDS			
Comment:	<p>Prior & this insp: Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Weeds remain at wellsite. Original Corrective Action date: 06/04/2018. Remains applicable. See photos #1, 2.</p>			
Corrective Action:	Weeds remain at wellsite from prior & this insp. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photos #1, 2.			Date: 06/04/2018
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Removed		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Removed		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0	<100 BBLS	PBV CONCRETE		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288246	Type:	WELL	API Number:	123-24562	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Battery Abandoned. ALL equipment removed. Last Prod: 03/2017. SI/TA. MIT requirement waived per variance Doc #401474555. Orange decommission tag for SI/TA status present. Locked Out Tagged Out (LOTO). (NOBLE)</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 06/21/2019 at approximately 16:09 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: FOSS - USX AA-66N63W /5SWSW Location ID: 306382 Location County: Weld County, Colorado Weather: Damp, from prior rain.</p> <p>While there, I observed: Well(s) - 1: Temporarily Abandoned (TA). Battery: Abandoned, ALL equipment removed. Reclamation progressing. Abandoned Centralized Battery formerly served 2 Location IDs (306382, 310381). Abandoned Battery GPS Coordinates SE Corner: 40.515428, -104.469150</p> <p>Follow-up to Field Inspection Report Doc. #684905466 dated 05/24/2018. 1 of 2 Corrective Actions appears addressed. 1.) Stained soil at crude oil tank loadout. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at crude oil tank loadout. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018. * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.</p> <p>1 of 2 Corrective Actions appears NOT addressed. 1.) Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f . Original Corrective Action date: 06/04/2018. Remains applicable. See photos #1, 2.</p> <p>1: NEW Corrective Actions observed on this inspection. 1.) Emergency number at wellsite is NOT valid. Refer to Rule 210.b. Post valid emergency number at wellsite. Comply w/ Rule 210.b. See photo #2. Corrective Action date: 07/26/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101054	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862099