

Inspection Photos

Location Name: Pit 44-2502-691

Facility ID: 296913

Inspection Date: June 13, 2019



Photo #1 – Aerial view of TEP Produced Water Facility ID 296913 (GISOnline Maps).



Photo #2 - Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pit 44-2502-691
Facility ID: 296913
Inspection Date: June 13, 2019



Photo #3 – Unused equipment near the flowline manifold.



Photo #4 – Unused equipment and debris near flowline manifold.



Inspection Photos
Location Name: Pit 44-2502-691
Facility ID: 296913
Inspection Date: June 13, 2019



Photo #5 – View of the eroding earthen berm around the tank battery and the stained Steel AST tank.



Photo #6 – Steel AST tank with staining.



Inspection Photos
Location Name: Pit 44-2502-691
Facility ID: 296913
Inspection Date: June 13, 2019



Photo #7 - Steel AST tank lacking tank capacity information.



Photo #8 – Uncapped poly pipes leading into the pit.



Inspection Photos
Location Name: Pit 44-2502-691
Facility ID: 296913
Inspection Date: June 13, 2019



Photo #9 – View of the pit looking north with sediment in the pit bottom and a rebar stake that has been driven through the pit liner. Condensate was also observed within the pit.



Photo #10 – Gaps (6-8 inches) in netting/fencing at poly pipe penetrations.



Inspection Photos
Location Name: Pit 44-2502-691
Facility ID: 296913
Inspection Date: June 13, 2019



Photo #11 – Uncontrolled access to the pit facility.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources