

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2019

Submitted Date:

06/26/2019

Document Number:

697600198

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 42640
Name of Operator: HYNDREX RESOURCES
Address: 1531 4TH AVE
City: GREELEY State: CO Zip: 80631-

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Lara-Mesa, Susana		cogcc@kpk.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

General Comment:

[followup inspection related to complaint 200446145](#)
[any reclamation requirments noted in past inspections may not be resolved at this time due to observations of significant adverse impacts to biological resources at the site](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			
Produced Water	Flow Line				
Comment:	spill 455229 reported by previous operator. suspected impacts from spill or remediation/reclamation efforts appear to remain at site with no cause of stunted crop growth known at this time.				
Corrective Action:	Develop a site investigation plan to determine cause of issues noted at site. Incorporate COA's yet to be specified by COGCC reclamation group in this site investigation plan. As part of site investigation the landowner must be contacted to discuss crop loss issues and consulted with on any remediation efforts. Submit form 27 describing proposed site investigation within 45 days. Initial plan may be revised through supplemental form 27 as information is gathered.				Date: 08/12/2019

In Containment: No

Comment:

spill 455229 was originally reported on 05242018 as having been discovered on 05/22/2018. An aerial image can be found on Google Earth with a capture date of 05312018. A annotated version of that aerial image is attached to this inspection. A near circular excavation area can be seen on the image and is labeled as spill excavation. Photos showing limited crop germination and growth in an approximate 100 foot by 30-50 foot area can be seen in two photos taken at the time of this inspection and these photos are attached

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600199	looking west across spill location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862554
697600200	looking east across spill location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862555
697600201	aerial image	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862556