

Inspection Photos

Location Name: SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851

Inspection Date: June 11, 2019



Photo #1 – Facility sign located at tank battery. Note accumulation of oil-stained soil beneath truck loadout and uncontrolled weeds in bermed area.



Photo #2 – Uncontrolled weeds and eroded berms at tank battery.



Inspection Photos

Location Name: SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851

Inspection Date: June 11, 2019



Photo #3 – Pump jack and wellhead are located northwest of tank battery, across lease road.



Photo #4 – View of wellhead from south.



Inspection Photos

Location Name: SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851

Inspection Date: June 11, 2019



Photo #5 – Accumulation of oil-stained soil beneath prime mover.



Photo #6 – Uncapped, unmarked flowline manifold west of pump jack. Note uncontrolled weeds in this location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851

Inspection Date: June 11, 2019



Photo #7 – Uncontrolled weeds near separator.

