

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2019

Submitted Date:

06/28/2019

Document Number:

698100018

**FIELD INSPECTION FORM**

Loc ID 323851 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 9 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
,		dnr_cogccenforcement@state.co.us	
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210985	WELL	SI	07/01/2014	GW	045-06743	SOUTH SHALE RIDGE 10-7	EI

**General Comment:**

[COGCC Environmental inspection of tank battery, separator, and pumping unit/wellhead.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Uncontrolled weeds throughout location, including inside of tank berm, near pump jack, and at heated separator. See photos.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>07/08/2019</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Accumulation of lube oil and oil-stained soil beneath prime mover. See photos.		
Corrective Action:	Remove and properly dispose of non-E&P waste, per Rule 907A.		Date: <u>07/28/2019</u>
PW/CO	Tank	<= 1 bbl	
Comment:	Historical accumulations of oil-stained soil at truck loadout. See photos.		
Corrective Action:	Remove and properly dispose of oily waste, per Rule 907.e.		Date: <u>07/28/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Accumulation of lube oil and oil-stained soil beneath prime mover. See photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/28/2019</u>
Type: Flow Line	# 2		
Comment:	Unused flowline risers near heated separator are not locked out/tagged out.		
Corrective Action:	Comply with Rule 603.f, Lock-out & tag out unused flowline risers within 24 hours of submittal of this Field Inspection Report., remove flowline riser within 30 days.		Date: <u>06/29/2019</u>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		
Comment:	Historical accumulations of oil-stained soil at truck loadout. See photos.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: <u>07/28/2019</u>

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type) _____	
--------------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment: <span style="color: blue;">Earthen berm eroded. Vegetation growth inside of bermed area. See photos.</span>				
Corrective Action: <span style="color: red;">Repair or install berms or other secondary containment devices per Rule 605.a.(4).</span>				Date: <u>07/28/2019</u>

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210985 Type: WELL API Number: 045-06743 Status: SI Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100028	20190611 Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864355</a>