

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

696300299

FIELD INSPECTION FORM

Loc ID 420650 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | |
| Kraich, Adam | | adam.kraich@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 420649 | WELL | PR | 11/01/2018 | OW | 123-32656 | RICHTER USX AB 27-05 | PR |
| 424570 | WELL | PR | 07/01/2018 | OW | 123-34089 | RICHTER USX AB27-65HN | PR |

General Comment:

| Location | | | |
|--|---|--------|-------------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate (x2) | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| Corrective Action: | <input style="width: 100%;" type="text"/> | | Date: _____ |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained soil at 2" valve on the bottom of the Hydraulic Power Unit, see photo #3 | | |
| Corrective Action: | For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e." | | Date: <u>07/31/2019</u> |
| Type | STORAGE OF SUPL | | |
| Comment: | Secondary containment at Hydraulic Power Unit has non-E & P waste, see photo #4 | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. | | Date: <u>07/31/2019</u> |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused chemical drum at Hydraulic Power Unit, see photo #5 | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: <u>07/31/2019</u> |
| Type | OTHER | | |
| Comment: | Stained Soil at Wellhead, see photo #6 | | |
| Corrective Action: | For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e." | | Date: <u>07/31/2019</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Bradenhead | # 2 | | corrective date |

| | | | |
|--------------------|----------------------------------|-------|--|
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # | | |
| Comment: | Hydraulic Pumping Unit | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 420649 Type: WELL API Number: 123-32656 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 424570 Type: WELL API Number: 123-34089 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary On Thursday 06/27/2019 at approximately 13:45 PM, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC. Richter USX AB 27-65HN, at Location #420650 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil at 2" valve on the bottom of the Hydraulic Power Unit, see photo #3, Comply with Rule 907.e. Corrective Action Date of 07.31.2019 Secondary containment at Hydraulic Power Unit has non-E & P waste, see photo #4, Comply with Rule 907A. Corrective Action Date of 07.31.2019 Unused chemical drum, see photo #5, Comply with Rule 603.f. Corrective Action Date of 07.31.2019 Stained soil at Wellhead, see photo #6, Comply with Rule 907.e. Corrective Action Date of 07.31.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | petrie | 06/28/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696300300 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864759 |