

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

687905047**FIELD INSPECTION FORM**Loc ID 333992 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300784	WELL	PR	08/02/2017	GW	067-09661	UTE 01A-20 3	PA
300787	WELL	PR	07/30/2009	GW	067-09662	UTE 01A-20 4	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

-UTE 01A-20 3 (067-09661) Is Plugged and abandoned with dryhole marker present on location. Form 6 Document# 401773032 submitted on 9/24/18 with expiration date of 4/9/2019.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	UTE 01A-20 3 production equipment onsite. Dry hole marker already established. equipment is unused including flowlines, pumpjack, horsehead, wellhead piping, VFD drivers for electric motor.		
Corrective Action:	Remove unused equipment from location per Rule 603.f.	Date:	09/28/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:	On produced water tank vent.		
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	1-4" disconnected flowline from PA well to separator that needs to be cut/capped. 1-4" flowline from producing wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from produced water tank pumping unit to offsite produced water gathering system. 2-4" flowlines from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and 1 dryhole marker.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD driven motors.		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	300784	Type:	WELL	API Number:	067-09661	Status:	PR	Insp. Status:	PA
Facility ID:	300787	Type:	WELL	API Number:	067-09662	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905048	Dryhole Marker/Unused equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865108</a>
687905049	Unused equipment/piping/flowlines	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865109</a>
687905050	Unused equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865110</a>